

non-responsive

---

non-responsive  
non-responsive  
non-responsive  
non-responsive

non-responsive non-responsive

non-responsive non-responsive

non-responsive

non-responsive

non-responsive

non-responsive

non-responsive non-responsive non-responsive non-responsive

non-responsive  
non-responsive

non-responsive non-responsive non-responsive non-responsive non-responsive

**Russ Maddox** <russtmaddox@Exemption 6>

12/08/2008 07:49 AM

To

Tara Martich/R10/USEPA/US@EPA, mel\_langdon@dec.state.ak.us

cc

Please respond to  
russtmaddox@Exemption 6

Subject

Discharge

Hi Tara and Mel,

This aerial photo shows the discharge mentioned in the previous email. A more direct alignment has been suggested to alleviate flood and maintenance concerns as indicated in the diagram.

Thanks for all of your efforts on behalf of our environment.

Regards, Russ

*(See attached file: IMG\_5480culvert-2.jpg)*